



SPOTTING GUIDE

	LINEAR.240	LINEAR.350	LINEAR.RGBW
COVE	<i>No Spotting</i>	<i>No Spotting</i>	<i>Spotting Visible</i>
FLUSH	<i>Spotting Visible</i>	<i>No Spotting</i>	<i>Spotting Visible</i>
PLASTER	<i>No Spotting</i>	<i>No Spotting</i>	<i>Spotting Visible</i>
LEAN	<i>No Spotting</i>	<i>No Spotting</i>	<i>Spotting Visible</i>
LINE	<i>No Spotting</i>	<i>No Spotting</i>	<i>Spotting Visible</i>