



SPOTTING GUIDE

	LINEAR.240	LINEAR.350	LINEAR.RGBW
COVE	No Spotting	No Spotting	Spotting Visible
FLUSH	Spotting Visible	No Spotting	Spotting Visible
PLASTER	No Spotting	No Spotting	Spotting Visible
LEAN	No Spotting	No Spotting	Spotting Visible
LINE	No Spotting	No Spotting	Spotting Visible

PLASTER.